

Work Permit # DRL-2012-027 Work Order

Job# ____ Activity# ____ See "Instructions for Filling out the Work Permit" contained in the Work Planning and Control for Experiments and Operations Subject Area.

1. Work request WCC fills out this section.																
Requester: Don Lynch		Date	:		Ext.: 2253					Dept/Div/Group: PO/PHENIX						
Other Contact person (if different	eques	ter): Carter B	iggs	<u>.</u>				Ext.: 7515								
Work Control Coordinator: Don Lynch					Start Date: 11/5/2012				Est. End Date: 11/16/2012							
Brief Description of Work: Add additional support to MuID Collar Holding Area in IR																
Building: 1008 Room: IR					Equipment: MuID Coll Area				Support Service Provider: Carpenters and PHENIX Technicians					IX Technicians		
2. WCC, Requester/Designee, Service Provider, and ESS&H (as necessary) fill out this section or attach analysis																
ESS&H ANALYSIS																
Radiation Concerns	Radiation Concerns			one			Airborne Contaminat			ion Radiation			NORM			
☐ Special nuclear materials involved, not			rify Isotope Special Materials			s Group			Radiological materials involved, notify			otify Lal	aboratory Nuclear Safety Officer			
Radiation Generating Devices:	graphy		☐ Moisture Density Gauge			☐Soil Density Gauges			[☐X-ray Equipment						
Safety and Security Concerns			None					☐ Transport of Haz/Rad		ad Mate] Pressuri	ized Systems		
Adding/Removing Walls or Roofs		T	☐ Critical Lift			Fumes/Mist/Dust*		☐ Magnetic Fields*				Railroad Work		l Work		
☐ Asbestos*		Ī	☐ Cryogenic			☐ Heat/Cold Stress		☐ Nanomaterials/particles		icles*		Rigging				
☐ Beryllium*		ĦΕ	☐ Electrical			☐ Hydraulic		☐ Noise*				☐ Silica*				
☐ Biohazard*		ĦΕ	☐ Elevated Work		-			☐ Non-ionizing Radiation*				☐ Security Concerns				
☐ Chemicals/Corrosives*		ŤΕ	☐ Excavation			Lead*		Oxygen Deficiency*					Suspect	/Counterfeit Items		
☐ Confined Space*		ΤĒ	Ergonomics*		☐ Material Handling		☐ Penetrating Fire Wa				Ī	☐ Vacuum				
* Safety Health Rep. Review Requ	uired		_ •			al Exceed DOE 151.1-C Levels							☐ Other			
Environmental Concerns						Non			☐ Work impacts Environmental Per							
☐ Atmospheric Discharges (rad/non-rad)					_	=			☐ Soil Activation/contamination				☐ Waste-Mixed			
☐ Chemical or Rad Material Sto	rage or	Use					iid Discharges	Г	7 Waste-	Clean			Г	1 Waste-F	Radioactive	
Cesspools (UIC)	- 3					☐ Oil/PCB Management				Hazardous			Ē	1 Waste-F	Regulated Medical	
☐ High water/power consumption	n				Ħ		I potential	Ħ		Industrial			Ī		ound Duct/Piping	
Waste disposition by:					_	— Орін росенцаі							Ħ	Other	oana Daoor iping	
Pollution Prevention (P2)/Waste	Minimi	izatio	n Opportunity	! :		No	Yes									
FACILITY CONCERNS		_	None Non			Intermittent Energy Release										
		1 6	☐ Electrical Noise				ential to Cause a Fals						Vibrations			
Access/Egress Limitations	3	Ħ	☐ Impacts Facility Use						☐ Temperature Change				Other			
☐ Configuration Management	Configuration Management		☐ Maintenance Work or			_			Utility Interruptions				Outo			
WORK CONTROLS			I Waintenance Work of			ii ventilation dystems										
Work Practices																
None	□ F:	xhaus	st Ventilation	Піс	ockout	t/Tag	out	Т	1 Spill Co	ontainment	ТГ	1 Secur	itv (s	see Instruc	ction Sheet)	
☐ Rene ☐						ockout/Tagout osting/Warning Signs					Other	curity (see Instruction Sheet)				
□ Barricades					caffolding-requires inspection		Ē		Warning Alarm (i.e. "high level")			☐ Electrical Inspection Required				
Personal Protective Equipm	ont											•				
None None	CIIL	Тг	☐ Ear Plugs			Glov	ves as appropriate	Г] Lab Co	nat				1 Safety G	Glasses as appropriate	
Coveralls		╅	☐ Ear Muffs		☐ Goggles			H	Respirator*				Safety Harness			
			e Shield			ТΓ	Shoe Covers	╁	Safet			T High v	h visibility cloths/vest			
							_ 51100 004010			., 011000		9 \	. 10101	, 5.00115/		
Permits Required (Permits must be valid when job is scheduled.) ☑ None ☐ Cutting/Welding					☐ Impair Fire Protection Systems											
Concrete/Masonry Penetration		Ī	☐ Digging/Core			Rad Work Permit-RWP No										
☐ Confined Space Entry			Drilling Electrical Working			☐ Other										
— ' Hot																
Dosimetry/Monitoring			7.11.101			1 -				1		_				
None			Heat Stress Monitor			Real Time Monito					☐ TLD					
☐ Air Effluent		┵	☐ Noise Survey/Dosime								Waste Characterization					
Ground Water		Į <u>∟</u>	O ₂ /Combustible Gas			_ 0 0					ner					
Liquid Effluent			Passive Vapor Monito			or Sorbent Tube/Filt			ter Pump							
Training Requirements (List specific training requirements)																
C-A User or equiv. , PHENIX Awareness																
Based on analysis above, the Review Team determines the risk, complexity, and coordination ratings below: If using the permit when all hazard ratings are low, only the following need to so Although allowed, there is no need to use back of form)								following need to sign: (
ESS&H Risk Level:						ate High			WCC: Don Lynch			Date:				
Complexity Level:									Service Provider:			Date	:			
Work Coordination:									Authorization to start Don Lynch Date:							
								/D	oportmor	nt/Division	ar thair a		-+ C	/M/CC/D	lanianaa)	

7.0/3k11e011.doc 1 (09/2011)

		ork plan (use attachments for detaile ifications, and personnel availability need to		e Attached					
Special Working Conditions Required	(e.g., Industrial Hygiene hold points	s or other monitoring)							
None	_								
Notifications to operations and Operat	ional Limits Requirements: None								
Post Work Testing, Notification or Doc	cumentation Required:	т.							
Job Safety Analysis Required: Ye	es 🛛 No	Review Done: X in se	Review Done: in series team						
that could impact ESS&H have been of	considered and controls established	m members were appropriate for the work the discording to BNL requirements. In addition have been identified and recorded on this p	n, this signature indicates that applica						
Title	Name (print)	Signature	Life #	Date					
ES&H Professional									
F&O Facility Project Manager									
Service Provider									
Work Control Coordinator	Don Lynch		20146						
Safety Health Representative									
Research Space Manager									
Other									
Other (PHENIX Escort)									
Required Walkdown Completed									
*Primary Reviewer									
permit is current/complete. Job Super	performing work have read and und	erstand the hazards and permit requirements ures also includes verification that worker trai							
Job Supervisor: Workers:	1:t_#.	Contractor Supervisor:	1:5-#.						
Workers:	Life#:	Workers :	Life#:						
			+						
Workers are encouraged to provide fe	edback on FSS&H concerns or on	ideas for improved job work flow. Use feedb	each form or space helow						
Workers are encouraged to provide to	edback on Lookin concerns of on	iudas ioi improvou job mont nom. Ood 100ab	ack form or space seron.						
5. Department/Division, or their	<u> </u>	<u> </u>							
Conditions are appropriate to start wor	rk: (Permit has been reviewed, wor	rk controls are in place and site is ready for jo							
Name:	Signature:	Life#:	Date:						
6. Worker provides feedback.									
Worker Feedback (use attached she	eets as necessary)								
a) WCM/WCC: Are there an	ny changes as a result of worker fee	edback? Yes No							
Note: See Work Planning and Control									
7. Post Job Review/Closeout: \	Work Control Coordinator (au	thorizing dept.) checks quality of co							
acceptable condition. (WCC car postings, procedures, etc., is initia		e to work supervisor.) The WCC ensu	ures that the change process to u	pdate drawings, placards					
Name:	Signature:	Life#:	Date:						
Comments:									

7.0/3k11e011.doc 2 (09/2011)

MuID Collar Holding support Upgrade

INTRODUCTION

The MuID collars are large heavy semi-cylindrical steel structures which are normally bolted to the south end of the Muon South Magnet (MMS) and surround the beampipe. The collars provide shielding against unwanted signals from the PHENIX IP to the Muon ID detectors.

Each shutdown the MuID collars must be removed to allow the MMS magnet to be moved south providing access to interior PHENIX detector components. The MuID collars are too large, however, to be transported completely out of the IR unless the East Carriage (EC) is moved out of the IR. The EC can not be moved out of the IR unless the MMS is moved south.

This "choreography" dilemma is addressed by having a small dedicated area in the southeast corner of the IR where the Collars can be stored temporarily after removal, thus allowing the MMS to be moved south, which in turn allows the EC to be moved to the Assembly Hall (AH).

The area where the collars are temporarily stored is raised from the IR floor to the level of the PHENIX track system using jackposts, aluminum i-beams and aluminum channels for structural support under a steel grating which allows venting for the area below the tracks, thus preventing accumulation of gases.

Currently the far west side of this area is insufficiently supported resulting in some damage to the grating. While imminent failure of the support structure is not indicated, the damage to the grating would become progressively worse, if not addressed to the point where failure of the support structure would become likely.

PHENIX engineering has determined that an additional aluminum i-beam and aluminum channels can easily be added to the existing support structure to address this situation. The details are provided below.

Procedures

All work described herein shall be coordinated and performed by PHENIX technicians and BNL bargaining unit carpenters as appropriate to the task and per bargaining unit contract with BNL. All working personnel shall have appropriate skills and training to accomplish the work described herein. All workers shall have and wear the appropriate personal protective equipment (PPE) for each task.

- 1. Prior to starting work on this upgrade, a barricade or other equivalent appropriate measures shall be provided around the work area to prevent potential fall accidents into the area while the grating is removed.
- 2. Remove the grating.
- 3. Remove the thin steel angles separating the gratings on the west end of the support structure.
- 4. Install the jack posts, ibeam and channels per the sketches below.
- 5. Make sure that the jack posts are set such that the grating will sit flat and level on all support surfaces.

- 6. Re-install the grating.7. Upon completion of this project, all work permit paperwork shall be completed, all unexpected problems and their solutions shall be recorded along with any other appropriate observations.



TECHNICAL NUPPORT 20-2

MuID Collar IR Holding Area Support

Existing Structural Support provided by aluminum i-beams supported at each end by jackposts (which also adjust for height) and a central channel. On top of these are grated covers (not shown). Existing support does no extend all the way west end of holding area.


Existing Support structure

10/25/2012



10/25/2012





10/25/2012




TECHNICAL SUPPORT 20-2





Height adjustment and load path to floor through "REDIPOST" jack posts under both ends of i-beams

10/25/2012 4



New collar support structure adds 2 additional channels (full length) plus an ibeam supported by 2 jack posts at the west end of the support area. This will improve weight distribution and prevent damage to the west end of the grating (not shown) as has been occurring.